



# Technical Bulletin

August, 2019

**Important note** — New **firmware** release UR190725 for the AM-Solution URA USB RS232 Adapter and F3190731x for the UHA USB Host Adapter

## USB RS232 Adapter (URA)

Release notes for UR190725:

- Daikin Decos IIIJ serial number download fix and USDA calibration proper dataset.
- Daikin Decos V(a) Zestia displayed version fix and download extension changed from .INV to .VOA.
- Daikin Decos IIIE software upload for older versions fix.



AMS3000-004 Firmware for URA

[UR190725](#) [Update Instruction](#) Click here for instruction and firmware link or visit our website at

[www.am-solution.com](http://www.am-solution.com)

## USB Host Adapter (UHA)

Release notes for F3190731x:

- Fix for programming software starting with co2\_xxxx and ca\_xxxx.
- Configuration cfxxxxx.ml3 recognized as proper config file.

AMS2000-003 Firmware for UHA - ML3 "Full"

[F3190731A](#)

AMS2000-012 Firmware for UHA - ML3 "Upload"

[F3190731S](#)

[Update Instruction](#)

AMS2000-013 Firmware for UHA - ML3 "Download"

[F3190731R](#)



Please be reminded that we have a repair service for the USB RS232 Adapter and USB Host Adapter. With this special offer we would like to support the aftermarket service of our innovative tools and protect your investment as long as we can. The repair price for the URA is €98,96 and for the UHA €35,53 net.

For repair request please contact our sales department at [sales@am-solution.com](mailto:sales@am-solution.com)

## YOUR PARTNER IN INNOVATION



[info@am-solution.com](mailto:info@am-solution.com)  
[www.am-solution.com](http://www.am-solution.com)

AM-Solution  
Hoogvlietsekerkweg 126a  
3194AM Hoogvliet  
The Netherlands  
+31 (0)10 7371019

AM-Solution  
Koddeweg 2  
3194DH Hoogvliet  
The Netherlands  
+31 (0)10 7371019

AM-Solution South Africa (Pty) Ltd.  
Unit G6—Millenium Business Park  
Stellenberg Road—Parow Industria  
Cape Town—South Africa  
+27 (0)71 8955646